

## ● Important Product Life Cycle Notification

<b>Instrument:</b>	<b>Ex-Vivo SkyScan™ 1074 (all)</b>
<b>Last Delivery:</b>	<b>2006</b>
<b>End of Service:</b>	<b>2014</b>
<b>Successor:</b>	<b>1174</b>

To ensure our customers are better able to plan for the future and continue work with minimal interruption, Bruker provides ongoing communication of product life cycle notifications, which can also be found here.

Please be advised that systems which enter the end of service phase will be effected by limited, or no, parts availability and restrictive service options.

To ensure continuity, we recommend contacting your local Bruker office to discuss replacement options.